Record of Water Well

Indiana Department of Natural Resources

Reference Number
987

EXIT ON TO 10TH ST FROM I 465 AND GO W ON 10TH ST TO COUNTRY CLUB RD, TURN N
ON COUNTRY CLUB RD AND GO TO 2626

Mar 09, 1992

Owner-ContractorNameAddressTelephoneOwnerTOM LINKS2626 COUNTRY CLUB RD(000) 291-0632DrillerHARNESS BROS2494 W 350 S DANVILLE IN(000) 539-6848OperatorDESTER HARNESSLicense: 137

Construction Details

Well Use: Home Drilling method: Rotary Pump type: Submersible
Depth: 135.0 Pump setting depth: 100.0 Water quality: CLEAR

CasingLength: 131.0Material: PVCDiameter: 4.0ScreenLength: 4.0Material: PVCDiameter: 4.0 Slot size: 40

Well Capacity Test Type of test: Air Test rate: 10.0 gpm for 1.0 hrs. BailTest rate: gpm for hrs.

Drawdown: 10.0 ft. Static water level: 60.0 ft. Bailer Drawdown ft.

Grouting Information Material: BENT Depth: from 3.0 to 120.0

Installation Method: PUMP Number of bags used: 8.0

Well Abandonment Sealing material: Depth: from to
Installation Method: Number of bags used:

Administrative County: MARION Township: 16N Range: 2E

Section: NW of the SW of the NW of Section 27 Topo map: CLERMONT

Grant Number:
Field located by:
Courthouse location by:
on:

Location accepted w/o verification by:

Subdivision name:

Lot number:

Ft W of EL: Ft N of SL: Ft E of WL: Ft S of NL:

Ground elevation: Depth to bedrock: Bedrock elevation: Aquifer elevation:

UTM Easting: UTM Northing:

 Well Log
 Top
 Bottom
 Formation

 1.0
 60.0
 CLAY GRAY

 60.0
 130.0
 CLAY BLUE

 130.0
 135.0
 GRAVEL

Comments SKETCH MAP