





LEGEND	
	DESTRUCT (DS)
	GAS VENT
	OR • REPAIR NUMBER (R)
	RUB SHEET
	LEAK DETECTION AND GROUND WATER DETECTION PIPES
	SUMP
	CAPPING



CASCADE SERVICES, LLC
3303 E CR 44
MIDLAND, TX 70705

SCALE: NTS	CLIENT: CHARGER SERVICES	LAYER: SECONDARY
DRAWN BY: C. GOWAN	PROJECT: SUMMIT EAST	MATERIAL: 40 MIL BLACK SMOOTH NOMINAL HDPE