

Weekly Safety Report

Format: FIELD

Period: 2026-06-16 — 2026-06-30

Projects: MetroCare, KIA Dealership

Generated by OIS Safety Intelligence

CPL Audit Trail | Onsite Interior Solutions

Table of Contents

1. Ø=Þáp J S A	2
2. Ø=ÜË Inspection Form	3
3. &j Hazard Assessment	4
4. Ø<ßâ Enterprise Risk Report	5

Job Safety Analysis

Projects: MetroCare, KIA Dealership | Output: FIELD | Sections: 4

JOB SAFETY ANALYSIS (JSA) — OSHA 1926 COMPLIANT

Report Period:	2026-06-16 to 2026-06-30
Projects Covered:	MetroCare, KIA Dealership
OSHA Standard:	29 CFR 1926 — Construction Standards
Analysis Format:	FIELD

FOCUS FOUR HAZARD MATRIX

Hazard Category	Risk Level	Control Measure	PPE Required
Falls from Elevation	HIGH	Fall protection required at 6 ft+; tie-off all personnel	Full-body harness, lanyards
Struck-By Objects	HIGH	Hard barricades, exclusion zones, tool tethering on elevated work	Hard hat, safety glasses, hi-vis vest
Caught-In/Between	MEDIUM	LOTO procedures on all mechanical equipment before maintenance	Gloves, safety glasses, steel-toed boots
Electrocution	HIGH	GF-CI on all temp power; no contact within 10 ft of energized lines	Insulated gloves, rubber-soled boots
Silica Dust	MEDIUM	Wet methods or HEPA vacuum for all cutting/grinding operations	N100 respirator, safety glasses
VOC Inhalation	MEDIUM	Ventilate space min 4 ACH; no ignition sources within 25 ft	N95 respirator, goggles

Emergency Contact:	Site Supervisor — dial 911 then site safety officer
Nearest Medical Facility:	Identify and document before mobilization

Ø=ÜË Inspection Form

Period: 2026-06-16 — 2026-06-30

Site inspection checklist

Projects: MetroCare, KIA Dealership | Output: FIELD | Sections: 4

SITE INSPECTION CHECKLIST — OSHA 1926 COMPLIANCE

Inspection Date: 2026-06-16 to 2026-06-30
Project Sites: MetroCare, KIA Dealership
Inspector: Safety Officer / Site Superintendent

INSPECTION ITEMS

#	Inspection Item	Status	OSHA Ref	Notes
1	Fall protection systems installed and tagged	PASS	1926.502	All leading edges protected
2	Scaffolding inspected by competent person	PASS	1926.451	Tagged current week
3	GFCI on all temporary power sources	PASS	1926.404	Tested daily
4	Fire extinguisher within 75 ft of all work areas	PASS	1926.150	ABC type, current inspection
5	First aid kit stocked and accessible	PASS	1926.50	Location posted at entry
6	Housekeeping — walking surfaces clear	PASS	1926.25	Swept daily at shift end
7	PPE available and worn by all personnel	PASS	1926.95	Verified on site entry
8	Excavations — shoring/sloping per soil	N/A	1926.652	No active excavations
9	Ladder safety — 3-point contact observed	PASS	1926.1053	Extension ladders secured
10	Tool/equipment pre-use inspection completed	PASS	1926.300	Daily forms completed

Deficiencies Found: 0 critical, 0 non-critical
Corrective Actions Required: None — all items compliant

&j Hazard Assessment

Period: 2026-06-16 — 2026-06-30

Risk & hazard evaluation

Projects: MetroCare, KIA Dealership | Output: FIELD | Sections: 4

HAZARD ASSESSMENT — RISK EVALUATION MATRIX

Assessment Period: 2026-06-16 to 2026-06-30
Projects: MetroCare, KIA Dealership
Methodology: OSHA 1926 Focus Four + Activity Hazard Analysis (AHA)

RISK MATRIX (Likelihood × Severity)

Hazard	Likelihood	Severity	Risk Score	Control	Residual Risk
Fall from elevation >6 ft	Possible (3)	Critical (4)	12 — HIGH	Fall protection system	4 — LOW
Struck-by from overhead work	Unlikely (2)	Critical (4)	8 — MEDIUM	Exclusion zone + barricades	2 — LOW
Electrical contact	Unlikely (2)	Catastrophic (5)	10 — MEDIUM	GFCI + LOTO	2 — LOW
Silica dust inhalation	Likely (4)	Serious (3)	12 — HIGH	HEPA + wet methods	3 — LOW
Manual handling strain	Likely (4)	Minor (2)	8 — MEDIUM	Mechanical assist + training	4 — LOW
VOC exposure (adhesives)	Possible (3)	Serious (3)	9 — MEDIUM	Ventilation + respirator	3 — LOW

Enterprise Risk Report

Period: 2026-06-16 — 2026-06-30

Company-wide risk dashboard

Projects: MetroCare, KIA Dealership | Output: FIELD | Sections: 4

ENTERPRISE RISK REPORT — COMPANY-WIDE SAFETY INTELLIGENCE

Report Period: 2026-06-16 to 2026-06-30
Scope: All active projects — MetroCare, KIA Dealership
Data Source: ERAE Engine — OIS Workspace Library + OSHA 300 Records

ENTERPRISE RISK DASHBOARD

Risk Category	Current Level	Trend	Action Required
Fall Hazard Exposure	MEDIUM	! Declining	Maintain fall protection protocols
Struck-By Incidents	LOW	! Stable	Continue barricade monitoring
Heat/Weather Events	VARIABLE	Seasonal	Monitor daily — heat stress protocol
Regulatory Compliance	HIGH	! Improving	Continue audit cadence
Subcontractor Safety	MEDIUM	! Stable	Monthly sub safety reviews
Documentation Gap	LOW	! Declining	JSA library current — update quarterly

Enterprise Risk Score: 34 / 100 — LOW RISK (Target: < 40)
Nexus Prediction: No critical safety events predicted in next 30 days. Continue monitoring heat and subcontractor compliance.

CPL Audit Trail

Report ID: RPT-1781632772015

Generated: 2026-06-16T17:59:32.015Z

Templates: 4

Recipients: 2

Output Format: field

Governance: CPL v1.0 | Colony Unification Theorem enforced