

Maintenance sheet version 10 for ablation area (tripod, one level)

Station name	QAS_M-V3
People present	JEB INSTE KOM p16+ Jan
Purpose	Maintenance installation / take-down / quick visit / emergency <i>Serve</i>
Date	5 Sep 2025

Notes:

PROMBIO Sample Site

Note: need to repair old SR50 before leaving for field

AWS to do list		Check after maintenance			
Part	Shipped (Y/N)	Replaced? (Y/N)	Number shipped/arrival	Number departure	
Radiometer	N	N			Clean? Y / N
Ablation hose assembly	N	N			No air in hose and bladder half full? Y / N
Iridium modem IMEI number	N	N			
Inclinometer/compass	N	N			Attached to the radiometer? Y / N
Satellite antenna	N	N			
Wind sensor	N	N			Black box pointing toward the radiometer (i.e., along the boom)? Y / N
Temperature / humidity assembly	N	Y			Fan spins? Y / N Sounds, OK? Y / N
HygroClip T/hum. assembly	Y	Y			NB: Rotronics (Y / N) could have a 40 °C offset. New or old type? NB: Luft sensor (Y / N)
Sonic ranger on AWS	Y	Y			Old sensor with new membrane? Y / N
Sonic ranger on stake	Y	Y			Old sensor with new membrane? Y / N NB: make sure not being buried next winter
Thermistor string	N	N			
Solar panel	N	N			Clean? Y / N NB: is not effective when partially covered
GPS antenna	N	N			At top of logger enclosure? Y / N
Logger box ID	N	N			CR1000 or CR1000X? ID number:
Logger enclosure	N	N			Replaced (including everything inside)? Y / N New desiccant bags? Y / N
Battery box	N	N			New box? Y / N New desiccant bags? Y / N
Stakes	Y	Y			New one(s) drilled in? Y / N Length of new stake(s) 8 m? Y / N
Tripod	N	N			New tripod? Y / N New sensor boom? Y / N

825 cm PTA hose is free to top marking "15m"

Station name	QAS_M-v3
Date	5 Sep.

Metadata maintenance

	Arrival	Departure
Time difference between logger clock and UTC ($\pm$ mm:ss)	11 sec	
Download data and/or change CF/SD Card (wait for green light)	Y / N	Y / N
Name of logger program	1.5 rev	same
Screen dump of values in fast scan mode	Y / N	Y / N
Photos of tripod, sensors, logger box wiring etc. (more is better)	Y / N	Y / N
Boom direction relative to north	192 ° true/magn.	same true/magn.
Box on wind sensor exactly towards mast? If not, measure.	same Y / N	30 W of Y / N
Radiometer exactly aligned with inclinometer? If not, measure.	Y / N	Y / N
Temperature / humidity height (bottom of casing – surface)	237 cm	same cm
Stake assembly standing?	Y / N / sort of	Y / N / sort of
Free length of stake	475 cm	277 cm
Height of ablation bladder fluid level above the ice surface	105 cm	105 cm
Vertical difference in surface height (at station – at hose) (approx.)	~ 25 cm	same cm
Length of thermistor string on surface from surface marking	315 out cm	same cm
Apparent damage to sensors? If yes, which?	Y / N	Y / N

Notes:

315 cm TC string is out / free
* $\pm$ 0.7 m bumpy surface.

Must-do at next visit:

New TC