sanas South African National Accreditation System

NON-CONFORMANCE, CORRECTIVE ACTION AND CLEARANCE REPORT

SANAS No.: T1195

Organisation Name: A Zurc Sky PTY LTD.

NC Report Number: NC 01

Area/Scope Assessed: Coal testing

Assessor / Inspector / Expert: N Chitiyza

PART 1: DETAILED OBSERVATION

The platform scale used for sample preparation (AU025PA) is Moved around When sample is weighed at different stages Posing an accuracy Risk

Signed (Representative):

Signed (Team Leader / Inspector):

MAJOR: ☒ MINOR: ☐

Reference No. of relevant Guide / Standard / Requirement: ISO/IEC 17025 Clause 7.4/6.4

Date: 07/04/26

PART 2: ROOT CAUSE ANALYSIS

(Provide an analysis of the extent and cause of the nonconformity)

PART 3: CORRECTIVE ACTION TAKEN

(Clearly indicate what corrective action was taken, and attach supporting evidence of implementation)

Date:

Signed (Representative):

PART 4: CORRECTIVE ACTION VERIFIED AND CLEARED

(Comment on whether the corrective action is sufficient and appropriate)

Date:

Signed: Assessor / Inspector/Expert:

PART 5: FOLLOW-UP AT NEXT ASSESSMENT

(Comment on the implementation of the corrective actions)

Date:

Signed: Assessor / Inspector/Expert:

©SANAS