CELLFEE

Battery Qualification & Listing — Synthetic Test Report

TEST DATA ONLY — NOT A REAL LAB REPORT OR SAFETY CERTIFICATE. All values below are fictional and intended to test your PDF field-extraction/model workflow. Do not use this document to purchase, transport, refurbish, deploy, or certify a battery.

1. Battery

Manufacturer	Asterion Energy Systems (fictional)
Model	AE-NMC-60-2021 (fictional)
Original vehicle	Demo EV-60 (fictional)
Chemistry	NMC
Serial number	EVB-KA-2048
Age (years)	5
Rated capacity (kWh)	60
Rated voltage (V)	3.7 (nominal cell voltage; pack voltage not supplied)
City (required)	Bengaluru, Karnataka, India
Complete pack or module (required)	Complete pack

2. Health report

Testing lab	CELLFEE-TEST-LAB (synthetic example; not a real laboratory)
Report ID	CELLFEE-REPORT-DEMO-0001
Test date	29 Oct 2026
State of Health (%)	81
Measured capacity (kWh)	48.6
Internal resistance (mΩ)	—
Report disclaimer	Synthetic demonstration data only. Not valid for purchasing, reuse, transport, warranty, or safety certification.

3. Price & contact

Asking price (₹, required)	₹180,000
Price negotiable	Yes
Condition	No visible external damage reported; full professional inspection still required
Known faults	No known faults reported by fictional seller; this is not proof that the battery is fault-free
Preferred contact	Phone
Your contact (private until you accept a buyer)	+91-90000-12345 (fictional test number)
Seller confirmation	Not signed — test report only

4. Machine-readable field inventory

Field key	Value
manufacturer	Asterion Energy Systems
model	AE-NMC-60-2021
original_vehicle	Demo EV-60
chemistry	NMC
serial_number	EVB-KA-2048
age_years	5
rated_capacity_kwh	60
rated_voltage_v	3.7
city	Bengaluru, Karnataka, India
pack_or_module	Complete pack
testing_lab	CELLFEE-TEST-LAB
report_id	CELLFEE-REPORT-DEMO-0001
test_date	2026-10-29
state_of_health_percent	81
measured_capacity_kwh	48.6
internal_resistance_milliohm	(blank)
asking_price_inr	180000
price_negotiable	Yes
condition	No visible external damage reported; full professional inspection still required
known_faults	No known faults reported by fictional seller; this is not proof that the battery is fault-free
preferred_contact	Phone
seller_contact	+91-90000-12345 (fictional test number)
seller_confirmation	Not signed — test report only

Data consistency note: 48.6 kWh is 81% of 60 kWh. The 3.7 V value is explicitly labeled as nominal cell voltage, because complete battery-pack voltage cannot be inferred from a cell-level value. Internal resistance is intentionally blank to test missing-field handling.