

Commissioning & Service Record

Fictional field form for AI extraction / service-history demo | Ref: DEMO-FORM-007

Important: This document is fictional material created for an AI-agent demonstration. Values and procedures must be validated against the actual appliance manual, installation standard and site conditions before field use.

1. Appliance / site record

Field	Demo entry
Site	Demo Residence - Cork
Appliance	Firebird Demo Heating Unit X24 (fictional)
Serial	DEMO-X24-2609017
Service date	08 Sep 2026
Engineer	Demo Engineer 04
Customer symptom	Pressure falls over 2-3 days; upstairs radiator occasionally cold

2. Measurements

Measurement	Before service	After service
System pressure - cold	0.7 bar	1.2 bar
System pressure - hot	2.7 bar	1.8 bar
Flow temperature	68 C	66 C
Return temperature	47 C	50 C
Observed Delta-T	21 C	16 C
Relief discharge evidence	Light staining	No discharge during test

3. Work notes

Demo only: engineer recorded a large initial cold-to-hot pressure swing, inspected the expansion-control arrangement, corrected the simulated issue under the fictional product procedure, restored approved cold pressure and tested through a heating cycle. No active visible leak was found during the visit.

4. Follow-up

Customer advised to monitor cold pressure. If pressure falls again, investigate hidden system water loss and re-check relief discharge. This record is designed so an AI agent can answer: 'What happened on the last visit?' or 'What were the before/after pressure readings?'