1. Inspection Report (Sample)

Property Details

- Property Type: Residential Apartment
- Location: Pune, Maharashtra
- Inspection Date: 10 April 2026

Observations

Living Room

- Wall paint shows **visible damp patches**
- Slight **paint peeling near ceiling corner**
- Musty odor detected

Bedroom

- Wooden flooring slightly **warped**
- Moisture detected near window frame
- No visible leakage source

6

Bathroom

- Minor **water seepage near shower area**
- Grout between tiles damaged
- Exhaust fan not working

Kitchen

- Sink pipe leakage observed
- Cabinet wood swelling
- No mold detected