

1. VESSEL INSPECTION DETAILS

Vessel ID:	WhatsApp_Image_2026-04-12_at_PM
Inspection Date:	2026-04-12 16:32:43
Report Number:	NautiCAI-2026-04-12-001
Inspection Type:	Automated Underwater Hull Assessment
Report Status:	COMPLETED - Audit Trail Generated

2. HULL CONDITION FINDINGS

Inspection Method:	Automated Underwater Inspection
Total Hull Coverage:	77.6284%
Overall Condition:	High
Fouling Areas Identified:	30

3. OFFICIAL COMPLIANCE RATING

FR-4 (Heavy Macrofouling - Critical!)

!! IMMEDIATE CLEANING REQUIRED !!

Required Action: URGENT: Immediate dry-dock cleaning required!

4. COMPLIANCE DECLARATION

This report was issued in accordance with IMO Biofouling Guidelines Resolution MEPC.207(62). All findings are fully repeatable and auditable.

Annotated inspection result - hull image with AI detections

