Inspection Report For - Alfa Romeo Giulia Quadrifoglio 2.9T V6 Quadrifoglio F

Basic Information

Car Make	Alfa Romeo
Car Model	Giulia Quadrifoglio 2.9T V6 Quad...
Model Trim	-
Model Year	2026
Chassis Number / VIN Number	213123812
Exterior Color	red
Body Type	123
Transmission	121233
Drive Displacement	1
Car Specifications	GCC SPEC
Production Year	2026
Mileage	36000 KM
Number of Keys	2
Number of Seats	6
Cylinders	wqjioejqw
Engine Size	123213
Engine Number	123123
Fuel	123123
Rim Size	123

Notes
qqweqweqwe

License Information

First Owner	Yes
Is the Car Mortgaged	Yes
Vehicle Category	132
Insurance Type	123
Registration Expiry Date	2026
Registered City / Plate	123123123
Plate Number	12312312wqe
TCN	123123

Service History

Service Pack	Yes
Service History	Yes
Last Serviced	123123
Warranty	Yes

External Body Condition

Front bumper	Pass	Rear bumper	Pass
Bonnet	Pass	Roof	Pass
Boot trunk	Pass	Driver front door	Pass
Driver front wing	Pass	Driver rear door	Pass
Driver rear quarter	Fail	Passenger front door	Pass
Passenger front wing	Pass	Passenger rear door	Pass
Passenger rear quarter	Pass	Driver front rim	Pass
Driver rear rim	Pass	Passenger front rim	Pass
Passenger rear rim	Pass	Front glass	Pass
Rear glass	Pass	Left glass	Pass
Right glass	Pass	Sunroof glass	Pass

Mechanical Components

Engine oil leak free	Pass	Engine compartment firewall	Pass
Engine fan	Pass	No abnormal engine odor	Pass
Brake hoses	Pass	Shock absorber	Pass
Tie rods	Pass	Steering	Pass
Axels	Pass	Transfer case	Pass
Clutch	Pass	Differential	Pass
Exhaust system	Pass	Under carriage	Pass
Braking system	Pass	Head lights	Pass
Warning lights	Pass	Air bag	Pass
Air condition and heat	Pass	Driving electronics	Pass
Navigation system	Pass	Windows and sun roof	Pass
Central locking	Pass	Horn and radio	Pass
Battery and battery cables	Pass	Belts and pulleys	Pass
Transmission oil leak free	Pass	Transmission system	Pass

Tyres and Accessories

Driver Side Front Tyre	Pass - 2026	Driver Side Rear Tyre	Pass - 2026
Passenger Side Front Tyre	Pass - 2026	Passenger Side Rear Tyre	Pass - 2026
Spare Tyre	Yes	Truck Tools Available	Yes
Service Book	Yes	Interior Seats	fabric

Inspection Notes

Driver rear quarter
qjweqwe

Interior Notes
qweqwe

Report Information

Report Status
Completed

Inspected By
Purchaser1

Inspected On
18 Oct 2026, 10:32

Branch
Al Quoz, Dubai, UAE

1. Front of vehicle



qwewqe

2. Front bumper



3. Front left three-quarter



qwe

4. Front right three-quarter



5. Left side



qwe

6. Right side



7. Rear of vehicle



qwe

8. Rear bumper



9. Rear left three-quarter



10. Rear right three-quarter



11. Bonnet



12. Roof



13. Front windscreen



14. Rear windscreen



15. Driver dashboard and odometer



16. Steering wheel



17. Front seats



18. Rear seats



19. Boot trunk



20. Engine bay



qweqwe

21. Driver front wheel and tyre



22. Driver rear wheel and tyre



qwewqe

23. Passenger front wheel and tyre



24. Passenger rear wheel and tyre

