CarVibeDubai
Vehicle inspection report

Inspection Report For - Jetour T2 Luxury 2025

Basic Information

Car Make	Jetour
Car Model	T2 Luxury
Model Trim	2.0TC I4 Luxury 4WD
Model Year	2025
Chassis Number / VIN Number	TEST-CHASSIS-2025
Exterior Color	Black
Body Type	SUV
Transmission	Automatic
Drive Displacement	4WD
Car Specifications	GCC
Production Year	2025
Mileage	51616 KM
Number of Keys	2
Number of Seats	5
Cylinders	I4
Engine Size	2000
Engine Number	-
Fuel	Gasoline
Rim Size	-

Notes
First owner, under warranty and service contract subject to confirmation.

License Information

First Owner	Yes
Is the Car Mortgaged	No
Vehicle Category	Private
Insurance Type	Full
Registration Expiry Date	-
Registered City / Plate	Dubai
Plate Number	-
TCN	-

Service History

Service Pack	Yes
Service History	Yes
Last Serviced	-
Warranty	Yes

External Body Condition

Front bumper	Pass	Rear bumper	Pass
Bonnet	Pass	Roof	Pass
Boot trunk	Pass	Driver front door	Pass
Driver front wing	Pass	Driver rear door	Pass
Driver rear quarter	Pass	Passenger front door	Pass
Passenger front wing	Pass	Passenger rear door	Pass
Passenger rear quarter	Pass	Driver front rim	Pass
Driver rear rim	Pass	Passenger front rim	Pass
Passenger rear rim	Pass	Front glass	Pass
Rear glass	Pass	Left glass	Pass
Right glass	Pass	Sunroof glass	Pass

Mechanical Components

Engine oil leak free	Pass	Engine compartment firewall	Pass
Engine fan	Pass	No abnormal engine odor	Pass
Brake hoses	Pass	Shock absorber	Pass
Tie rods	Pass	Steering	Pass
Axels	Pass	Transfer case	Pass
Clutch	Pass	Differential	Pass
Exhaust system	Pass	Under carriage	Pass
Braking system	Pass	Head lights	Pass
Warning lights	Pass	Air bag	Pass
Air condition and heat	Pass	Driving electronics	Pass
Navigation system	Pass	Windows and sun roof	Pass
Central locking	Pass	Horn and radio	Pass
Battery and battery cables	Pass	Belts and pulleys	Pass
Transmission oil leak free	Pass	Transmission system	Pass

Tyres and Accessories

Driver Side Front Tyre	Pass - 2025	Driver Side Rear Tyre	Pass - 2025
Passenger Side Front Tyre	Pass - 2025	Passenger Side Rear Tyre	Pass - 2025
Spare Tyre	Yes	Truck Tools Available	Yes
Service Book	Yes	Interior Seats	leather

Report Information

Report Status
Completed

Inspected By
Purchaser 1

Inspected On
13 Sept 2026, 14:30

Branch
Al Quoz, Dubai, UAE

Front of vehicle checked; no visible damage in this sample.

1. Front of vehicle



Front bumper checked; no visible damage in this sample.

2. Front bumper



Front left three-quarter checked; no visible damage in this sample.

3. Front left three-quarter




Front right three-quarter checked; no visible damage in this sample.

4. Front right three-quarter




Left side checked; no visible damage in this sample.

5. Left side



Right side checked; no visible damage in this sample.

6. Right side




Rear of vehicle checked; no visible damage in this sample.

7. Rear of vehicle



Rear bumper checked; no visible damage in this sample.

8. Rear bumper



Rear left three-quarter checked; no visible damage in this sample.

9. Rear left three-quarter




Rear right three-quarter checked; no visible damage in this sample.

10. Rear right three-quarter




Bonnet checked; no visible damage in this sample.

11. Bonnet



Roof checked; no visible damage in this sample.

12. Roof




Front windscreen checked; no visible damage in this sample.

13. Front windscreen




Rear windscreen checked; no visible damage in this sample.

14. Rear windscreen



Driver dashboard and odometer checked; no visible damage in this sample.

15. Driver dashboard and odometer




Steering wheel checked; no visible damage in this sample.

16. Steering wheel




Front seats checked; no visible damage in this sample.

17. Front seats



Rear seats checked; no visible damage in this sample.

18. Rear seats




Boot trunk checked; no visible damage in this sample.

19. Boot trunk




Engine bay checked; no visible damage in this sample.

20. Engine bay



Driver front wheel and tyre checked; no visible damage in this sample.

21. Driver front wheel and tyre




Driver rear wheel and tyre checked; no visible damage in this sample.

22. Driver rear wheel and tyre



Passenger front wheel and tyre checked; no visible damage in this sample.

23. Passenger front wheel and tyre



Passenger rear wheel and tyre checked; no visible damage in this sample.

24. Passenger rear wheel and tyre

