

HABS
OHIO
7-BEL,
8-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

4815 Guernsey St. (House)
Bellaire,
Belmont County
Ohio

HABS NO. OH-2323

Photographer: (Views 1-13) Ben Schneider
(Views 14-26) Ben Schneider

June 14, 1990
August 26, 1991

- OH-2323-1 Overall view southwest of east front
- OH-2323-2 View west, east elevation
- OH-2323-3 View west, east facade
- OH-2323-4 View north, east front and north side
- OH-2323-5 View south of north side
- OH-2323-6 View south, north side
- OH-2323-7 View southeast, north and west sides
- OH-2323-8 View east, west side (rear)
- OH-2323-9 Detail of wide overhang eave, boxed with brackets
and dormers
- OH-2323-10 Detail east dormer and chimney
- OH-2323-11 View northeast, garage to left
- OH-2323-12 View northwest, south side of garage
- OH-2323-13 First floor, foyer and detail interior of front
door, looking east
- OH-2323-14 First floor, foyer and staircase, looking southwest
- OH-2323-15 First floor, details of stairs, looking south
- OH-2323-16 First floor, stairs featuring newel post, looking
west

Index to Photographs
4815 Guernsey Street (House)
HABS No. OH-2323 (Page 2)

OH-2323-17	First floor, northeast room, east wall and pocket doors
OH-2323-18	First floor, northeast room, north wall, marbleized slate mantel
OH-2323-19	First floor, northwest room, west wall marbleized slate mantel
OH-2323-20	First floor, northwest room, detail of north floor parquet
OH-2323-21	First floor, dining room, north wall
OH-2323-22	First floor, dining room, south wall
OH-2323-23	Second floor, hallway, looking south
OH-2323-24	Second floor, northeast room, northeast corner
OH-2323-25	Second floor, southwest room, northeast corner
OH-2323-26	Attic, looking east