RESTRICTED — FOR OFFICIAL USE ONLY

EVIDENCE ANALYSIS REPORT

Alfa Hawk — AI Evidence Analysis Platform | Alfa Labs

Case Number:	Not Provided	**Report ID:**	RPT-3EC63894
Date:	14 March 2026	**Time:**	17:05:50 IST
Officer ID:	Not Provided	**Case Description:**	

Case Description: Not Provided

EVIDENCE FILE DETAILS

Filename:	accident_000.mp4
Media Type:	video
MIME Type:	video/mp4
File Size:	4.41 MB
Dimensions:	852 × 480 pixels
Duration:	0m 8s
Frame Rate:	30.0 FPS
Uploaded:	2026-03-14T17:05:18.003930

1. EXECUTIVE SUMMARY

The video evidence captures a first-person perspective from a motorcycle traveling on a highway. The motorcycle appears to approach and make contact with the rear of a sport utility vehicle (SUV), leading to a loss of control and the camera falling to the ground. The camera then records the ground and sky as it appears to slide or tumble.

KEY EVIDENCE OBSERVATIONS

• A motorcycle, from which the video is recorded, is observed traveling on a multi-lane highway (F1).

• The motorcycle approaches a silver Honda CR-V SUV, with license plate '5FVD634' visible on its rear (F2).

• Visual evidence suggests contact between the front of the motorcycle and the rear of the SUV (F3).

• Following the apparent contact, the camera's perspective rapidly shifts and disorients, consistent with a fall or impact (F4).

• The camera subsequently records views of the asphalt ground and the sky, indicating it is no longer mounted on the motorcycle (F6).

2. EVIDENCE INTEGRITY

SHA-256 Hash:	Not computed
File Size:	4.41 MB
Media Format:	video/mp4
Resolution:	852 × 480
Frame Rate:	30.0 FPS
Duration:	0m 8s
Codec:	h264
Processing Timestamp:	2026-03-14T17:05:18.003930

3. VIDEO QUALITY ASSESSMENT

Resolution Rating:	Medium
Lighting Quality:	Clear
Motion Blur:	Minimal initially, high during and after impact
ID Reliability:	High for vehicles and general environment, low for specific details during dislodgement.

4. SCENE DESCRIPTION

The scene is a multi-lane highway or freeway, with other vehicles present. Buildings and trees are visible in the background along the roadside. The road surface appears to be asphalt.

Camera Perspective:

Position: The camera is mounted on a motorcycle, providing a first-person, forward-facing perspective from the rider's viewpoint. After 00:00:04, the camera appears to be dislodged and records from a ground-level, tumbling perspective.
Field of View: The initial field of view is wide, encompassing the motorcycle's handlebars, dashboard, and the road ahead. After dislodgement, the field of view becomes erratic, showing ground and sky.
Limitations: Initial visibility is clear. After 00:00:04, rapid motion and proximity to the ground introduce significant motion blur and disorientation, limiting clear observation of specific details.

5. INCIDENT RECONSTRUCTION

Phase	Description	Time Range	Severity	Evidence
1	The motorcycle is observed traveling on a highway, maintaining a consistent speed and approaching a silver SUV in the same lane. The rider's gloved hands are visible on the handlebars.	00:00:00-00:00:02	LOW	F1
2	The motorcycle closes the distance to the SUV. The rear of the SUV, including its license plate '5FVD634' and 'HONDA' spare tire cover, becomes clearly visible. Apparent contact occurs between the motorcycle and the SUV.	00:00:02-00:00:04	MEDIUM	F3

3	Immediately following the apparent contact, the camera's perspective becomes highly disoriented, rapidly shifting between views of the ground and sky. Sounds consistent with scraping and impact are audible. The camera appears to be dislodged and tumbling or sliding on the ground.	00:00:04-00:00:08	HIGH	F5

6. PERSONS OF INTEREST

P-ID	Description	Observed Role	Visibility	Seen	Actions
P1	The individual operating the motorcycle. Only gloved hands are visible on the ha	motorcycle operator/passenger	Low (only hands visible)	00:00:00-00:00:10	Operating a motorcycle (F1); Hands visible on handlebars (F1)

7. WEAPONS & OBJECTS DETECTED

#	Object	Timestamp	Confidence	Held By	Evidence Ref
1	Motorcycle	00:00:00	High (90%)	N/A	F1
2	SUV	00:00:02	High (90%)	N/A	F2

Motorcycle: A white sport motorcycle, from which the video is recorded. Parts of the dashboard, windshield, and handlebars are visible.

SUV: A silver Honda CR-V sport utility vehicle, observed ahead of the motorcycle. Its rear spare tire cover with 'HONDA' lettering and license plate '5FVD634' are visible.

8. CHRONOLOGICAL TIMELINE

Seq.	Time	Event Description
1	00:00:00	Motorcycle is observed traveling on a highway (Frame F1)
2	00:00:02	Motorcycle approaches a silver Honda CR-V SUV, license plate '5FVD634' visible (Frame F2)
3	00:00:03	Apparent contact between the motorcycle and the rear of the SUV (Frame F3)
4	00:00:04	Camera view becomes disoriented, consistent with a fall or impact (Frame F4)
5	00:00:06	Camera records views of the ground and sky, indicating it is on the ground (Frame F6)

9. RISK & THREAT ASSESSMENT

Threat Level: HIGH

Risk Factors: High-speed environment, potential for severe injury due to vehicle collision, uncontrolled movement of the motorcycle and rider after impact.

Justification: The observable event involves a collision between a motorcycle and an SUV on a highway, which inherently carries a high risk of injury or further incident.

Recommended Response: Further investigation into the circumstances leading to the collision, assessment of participant status, and potential medical evaluation for the motorcycle operator.

10. AI CONFIDENCE MATRIX

Detection Type	Confidence Level	System Estimate
Object Recognition	UNKNOWN	75%
Scene Understanding	UNKNOWN	75%
Event Reconstruction	UNKNOWN	75%
Identity Consistency	UNKNOWN	75%

11. AI PROCESSING DISCLOSURE

Evidence media was analyzed using an external AI multimodal vision model (Google Gemini). Media was transmitted temporarily to the AI service for analysis and was deleted from the AI provider's servers immediately after processing. The AI service does not retain or store any evidence data. No evidence data is stored by this platform.

12. EVIDENCE HANDLING & CHAIN OF PROCESSING

The uploaded media file was processed entirely in volatile memory. No copy of the evidence file, extracted frames, or analysis results are stored in persistent storage by this platform. All processing artifacts are destroyed after report generation and session expiry.

Processing Steps:

1. Evidence file uploaded to in-memory buffer
2. SHA-256 hash computed for integrity verification
3. Media metadata extracted (resolution, codec, duration)
4. Video uploaded to AI service for multimodal analysis
5. AI analysis results received as structured JSON
6. Structured forensic report compiled from analysis
7. PDF report generated in-memory
8. Evidence file deleted from AI service servers
9. All in-memory artifacts scheduled for automatic cleanup

APPENDIX A: EVIDENCE EXHIBITS

Additional Evidence Frames

00:00:00

00:00:02

00:00:04

00:00:06

00:00:08

00:00:08

APPENDIX B: EVIDENCE FRAME INDEX

Ref	Timestamp	Description	Findings
F1	00:00:00	Frame at 00:00:00	—
F2	00:00:02	Frame at 00:00:02	—
F3	00:00:04	Frame at 00:00:04	—
F4	00:00:06	Frame at 00:00:06	—
F5	00:00:08	Frame at 00:00:08	—
F6	00:00:08	Frame at 00:00:08	—

REPORT CERTIFICATION

This report has been generated by an automated AI-powered evidence analysis system. All findings should be independently verified by qualified investigating officers before being used in legal proceedings.

Generated by: Alfa Hawk — AI Forensic Evidence Report Generator | Alfa Labs

Generated at: 14 March 2026, 17:05:50 IST

Confidence Score: 0%

Report Integrity Hash (SHA-256):

`ac3570c964c34030c9dd7271522331b128a105870f8ad6c2b7f88dfc895858a3`

Investigating Officer

Name: _____

Rank: _____

Badge/ID: _____

Date: _____

Reviewing Officer

Name: _____

Rank: _____

Badge/ID: _____

Date: _____