Condition Report

Property Details

Address:

Created On:25/01/2023 4:04:49 AM

Landlord Name: Tenant Name:

MRB Sharehouse Managers

Date of Inspection: 2023-01-25T00:00:00.000

Status:Signed by both Landlord & Tenant

Entrance / Hall

	Landlord			Tenant
	Clean	Undamaged	Working	Agrees?
walls/picture hooks	● Yes ○ No	● Yes ○ No	● Yes ○ No	● Yes ○ No
Comments (Max. 500 characters)	yes, working			agreed

	Clean	Undamaged	Working	Agrees?
doors/doorway frames	● Yes ○ No	● Yes ○ No	● Yes ○ No	○ Yes ● No
Comments (Max. 500 characters)	okay			Don't agree.

	Clean	Undamaged	Working	Agrees?
windows/screens/ window safety devices	○ Yes ● No	○ Yes ● No	○ Yes ● No	● Yes ○ No

Comments
(Max. 500 characters)

unclean, damaged but working

agreed

	Clean	Undamaged	Working	Agrees?
ceiling/light fittings	● Yes ○ No	○ Yes ● No	○ Yes ● No	● Yes ○ No

Comments
(Max. 500 characters)

clean but not working

agreed

	Clean	Undamaged	Working	Agrees?
blinds/curtains	○ Yes ● No	● Yes ○ No	○ Yes ● No	○ Yes ● No

Comments
(Max. 500 characters)

u, u w

There are some issues

	Clean	Undamaged	Working	Agrees?
lights/power points /door bell	○ Yes ● No	○ Yes ● No	○ Yes ● No	● Yes ○ No

Comments
(Max. 500 characters)

not working

agree

	Clean	Undamaged	Working	Agrees?
skirting boards	Yes	Yes	Yes	Yes
	No	No	No	No

Comments
(Max. 500 characters)

there are some issues

working

	Clean	Undamaged	Working	Agrees?
floor coverings	Yes	Yes	Yes	Yes
	No	No	No	No

Comments
(Max. 500 characters)

no , don't agree

in good condition

Additional Comments

see issues in pictures

Additional Comments

(Max. 500 characters)

enterance hall is in good condition

Bedroom

	Clean	Undamaged	Working	Agrees?
walls/picture hooks	Yes / No	Yes / No	Yes / No	Yes / No
	No	No	No	No

Comments
(Max. 500 characters)

working

don't agree

	Clean	Undamaged	Working	Agrees?
built-in wardrobes/shelves	Yes / No	Yes / No	Yes / No	Yes / No
	No	No	No	Yes

Comments
(Max. 500 characters)

not working

agree

	Clean	Undamaged	Working	Agrees?
doors/doorway frames	Yes / No	Yes / No	Yes / No	Yes / No
	No	No	No	No

Comments
(Max. 500 characters)

working

don't agree

	Clean	Undamaged	Working	Agrees?
windows/screens/ window safety devices	Yes / No	Yes / No	Yes / No	Yes / No
	No	No	No	Yes

Comments
(Max. 500 characters)

not working

yes

	Clean	Undamaged	Working	Agrees?
ceiling/light fittings	Yes / No	Yes / No	Yes / No	Yes / No

Comments
(Max. 500 characters)

working

don't

	Clean	Undamaged	Working	Agrees?
blinds/curtains	Yes / No	Yes / No	Yes / No	Yes / No

Comments
(Max. 500 characters)

all ok

agreed

	Clean	Undamaged	Working	Agrees?
lights/power points	Yes / No	Yes / No	Yes / No	Yes / No

Comments
(Max. 500 characters)

has some issues

agreed

	Clean	Undamaged	Working	Agrees?
skirting boards	Yes / No	Yes / No	Yes / No	Yes / No

Comments
(Max. 500 characters)

working

agreed

	Clean	Undamaged	Working	Agrees?	
floor coverings	Yes	Yes	Yes	Yes	No
	No	No	No		

Comments
(Max. 500 characters)

agreed

not working

Additional Comments

picts attached

Additional Comments

(Max. 500 characters)

all okay

Security and Safety

	Clean	Undamaged	Working	Agrees?	
external door locks	Yes	Yes	Yes	Yes	No
	No	No	No		

Comments
(Max. 500 characters)

ok

	Clean	Undamaged	Working	Agrees?	
window locks	○ Yes ● No	● Yes ○ No	● Yes ○ No	○ Yes	● No

Comments
(Max. 500 characters)

some issues

not okay

Additional Comments

Additional Comments

(Max. 500 characters)

ok

General

	Clean	Undamaged	Working	Agrees?	
heating/air conditioning	● Yes ○ No	● Yes ○ No	● Yes ○ No	● Yes	○ No

Comments
(Max. 500 characters)

ok

agree

	Clean	Undamaged	Working	Agrees?	
staircase/handrails	Yes	Yes	Yes	Yes	No
	No	No	No		

Comments
(Max. 500 characters)

dont

some issues found

Additional Comments

file attached

Additional Comments

(Max. 500 characters)

Maintenance required

Health Issues

			Agrees?	
Are there are any signs of mould and dampness?	Yes	No	Yes	No

agree

			Agrees?	
Are there any pests and vermin?	Yes	No	Yes	No

dont agree

Has any rubbish been left on the premises?	◉ Yes	○ No	Agrees? ○ Yes ◉ No
			agree

ok

Additional Comments

(Max. 500 characters)

Communication Facilities

a telephone line is connected to the residential premises	◉ Yes	○ No	Agrees? ○ Yes ◉ No
			don't agree
an internet line is connected to the residential premises	◉ Yes	○ No	Agrees? ○ Yes ◉ No
			agree

Additional Comments

(Max. 500 characters)

Water Efficiency Devices

all showerheads have a maximum flow rate of 9 litres per minute	(•) Yes	( ) No	Agrees? (•) Yes ( ) No agree
all water taps and single mixer taps hand basins have a maximum flow rate of 9 litres per minute	(•) Yes	( ) No	Agrees? ( ) Yes (•) No don't agree
no leaking taps on residential premises	(•) Yes	( ) No	Agrees? ( ) Yes (•) No there are some issues

Water meter reading:	343434

Additional Comments

(Max. 500 characters)

ok

Approximate dates when work last done on residential premises

Installation of water efficiency measures:	25/01/2023
Painting of premises (external):	26/01/2023

Painting of premises (internal): 27/01/2023

Flooring laid/replaced/cleaned: 28/01/2023

Landlord’s promise to undertake work:

(Skip if not required)

The landlord agrees to undertake the following cleaning, repairs, additions or other work during the tenancy:

All repair work to be done before tenancy starts.

The landlord agrees to complete that work by: 31/01/2023

25/01/2023 10:49:48 AM Landlord Signature



Tenant Signature

Entrance / Hall

Photos added by Landlord

SHAREHOUSE

Photos added by Tenant

SHAREHOUSE

Bedroom

Photos added by Landlord

SHAREHOUSE

SHAREHOUSE

4
SHAREHOUSE

Photos added by Tenant

SHAREHOUSE

Security and Safety

Photos added by Landlord

SHAREHOUSE

Photos added by Tenant

SHAREHOUSE

General

Photos added by Landlord

SHAREHOUSE

Photos added by Tenant

SHAREHOUSE