Condition Report

Property Details

Address:Malvern Street, Bayswater VIC, Australia

Created On:13/01/2023 4:18:28 PM

Landlord Name:Tenant Name:

Atif

Date of Inspection:

Status:???Status:

??

Entrance / Hall

	Landlord			Tenant
	Clean	Undamaged	Working	Agrees?
walls/picture hooks	● ○	● ○	● ○	○ ●
Comments (Max. 500 characters)	clean, undamage, working			disagree

	Clean	Undamaged	Working	Agrees?
doors/doorway frames	● ○	○ ●	● ○	○ ●
Comments (Max. 500 characters)	clean,damaged,working			disagreed

	Clean	Undamaged	Working	Agrees?
windows/screens/ window safety devices	● ○	● ○	○ ●	○ ●
Comments (Max. 500 characters)	clean,undamaged,not working			agreed

	Clean	Undamaged	Working	Agrees?
ceiling/light fittings	●	●	●	●
Comments (Max. 500 characters)	unclean,undamaged,not working			agree

	Clean	Undamaged	Working	Agrees?
blinds/curtains	●	●	●	●
Comments (Max. 500 characters)	clean,undamaged,working			disagree


	Clean	Undamaged	Working	Agrees?
lights/power points /door bell	●	●	●	●
Comments (Max. 500 characters)				agreed

	Clean	Undamaged	Working	Agrees?
skirting boards	●	●	●	●
Comments (Max. 500 characters)				agreed

	Clean	Undamaged	Working	Agrees?
floor coverings	●	●	●	●
Comments (Max. 500 characters)				disagreed

some issues in enterance hall found.

Attached Photos







Hall is in working condition.

Additional Comments

(Max. 500 characters)

Bedroom

	Clean	Undamaged	Working	Agrees?
walls/picture hooks	● ○	● ○	● ○	● ○

clean, undamage, working

agreed

Comments
(Max. 500 characters)

	Clean	Undamaged	Working	Agrees?
built-in wardrobes/shelves	●	●	●	disagree
Comments (Max. 500 characters)	clean,damaged,working			

	Clean	Undamaged	Working	Agrees?
doors/doorway frames	●	●	●	disagree
Comments (Max. 500 characters)	clean,undamaged,not working			

	Clean	Undamaged	Working	Agrees?
windows/screens/ window safety devices	●	●	●	agreed
Comments (Max. 500 characters)				

	Clean	Undamaged	Working	Agrees?
ceiling/light fittings	●	●	●	ok
Comments (Max. 500 characters)				

	Clean	Undamaged	Working	Agrees?
blinds/curtains	●	●	●	issues
Comments (Max. 500 characters)				

	Clean	Undamaged	Working	Agrees?	
lights/power points	○ ●	○ ●	○ ●	○	●

not working

Comments
(Max. 500 characters)

	Clean	Undamaged	Working	Agrees?	
skirting boards	○ ●	● ○	○ ●	○	●

uc, ud, nw

Comments
(Max. 500 characters)

	Clean	Undamaged	Working	Agrees?	
floor coverings	● ○	○ ●	○ ●	●	○

ok

Comments
(Max. 500 characters)

floor covering is okay

bedroom looks ok

Attached Photos







Bedroom has some issues but in good working condition.

Additional Comments

(Max. 500 characters)

Security and Safety

	Clean	Undamaged	Working	Agrees?
external door locks	● ○	● ○	● ○	● ○

agree

Comments
(Max. 500 characters)

external door locks in working condition

	Clean	Undamaged	Working	Agrees?
window locks	● ○	○ ●	● ○	○ ●

disagreed

Comments
(Max. 500 characters)

working condition

saftey and security looks ok

Attached Photos









Additional Comments

(Max. 500 characters)

No issue in security and safety

General

	Clean	Undamaged	Working	Agrees?
heating/air conditioning	● ○	● ○	● ○	● ○

Comments
(Max. 500 characters)

ok

	Clean	Undamaged	Working	Agrees?
staircase/handrails	○ ●	● ○	● ○	○ ●

Comments
(Max. 500 characters)


okay

disagreed

okay okay

Attached Photos







general condition is good

Additional Comments

(Max. 500 characters)

Health Issues

Are there are any signs of mould and dampness?	Yes	No	Agrees?
	●	○	● ○

Are there any pests and vermin?	Yes ○	No ●	Agrees? ○ ● disagree
Has any rubbish been left on the premises?	Yes ●	No ○	Agrees? ● ○ ok

Additional Comments

yes, no yes

(Max. 500 characters)

Communication Facilities

a telephone line is connected to the residential premises	Yes ○	No ●	Agrees? ○ ● disagreed
an internet line is connected to the residential premises	Yes ●	No ○	Agrees? ● ○ ag

Additional Comments

No, yes

(Max. 500 characters)

Water Efficiency Devices

all showerheads have a maximum flow rate of 9 litres per minute	Yes ○	No ●	Agrees? ○ ● disagreed
all water taps and single mixer taps hand basins have a maximum flow rate of 9 litres per minute	Yes ●	No ○	Agrees? ● ○ agree
no leaking taps on residential premises	Yes ○	No ●	Agrees? ○ ● disagreed

Water meter reading: 34343

Additional Comments

Water Efficiency Devices in working condition

(Max. 500 characters)

Approximate dates when work last done on residential premises

Installation of water efficiency measures: 13/01/2023

Painting of premises (external): 14/01/2023

Painting of premises (internal): 15/01/2023

Flooring laid/replaced/cleaned: 16/01/2023

Landlord’s promise to undertake work:

(Skip if not required)

The landlord agrees to undertake the following cleaning, repairs, additions or other work during the tenancy:

Work will be done before the start of the tenancy

The landlord agrees to complete that work by: 31/01/2023