Condition Report

Property Details

Address:Bannu Adda, Dera Ismail Khan, Pakistan

Created On:23/11/2023 07:08:38

Landlord Name:Tenant Name:

Kashif

Date of Inspection:2023-11-23T00:00:00.000

Status:Completed

Bedroom

	Landlord			Tenant
	Clean	Undamaged	Working	Agrees?
walls/picture hooks	☑	☑	☑	☑
Comments (Max. 500 characters)	testing			yes, agreed.

	Clean	Undamaged	Working	Agrees?
built-in wardrobes/shelves	☑	☐	☑	☑
	☐	☒	☐	☐
Comments (Max. 500 characters)	testing			yes, agreed.

	Clean	Undamaged	Working	Agrees?
doors/doorway frames	☑	☐	☑	☐
	☐	☒	☐	☒
Comments (Max. 500 characters)				no

	Clean	Undamaged	Working	Agrees?	
windows/screens/ window safety devices	☐	☑	☐	☐	
	☒	☐	☒	☒	
Comments (Max. 500 characters)					no

	Clean	Undamaged	Working	Agrees?	
ceiling/light fittings	☑	☐	☑	☐	
	☐	☒	☐	☒	
Comments (Max. 500 characters)					

	Clean	Undamaged	Working	Agrees?	
blinds/curtains	☐	☐	☐	☑	
	☒	☒	☒	☐	
Comments (Max. 500 characters)					yes

	Clean	Undamaged	Working	Agrees?	
lights/power points	☐	☐	☐	☐	
	☒	☒	☒	☒	
Comments (Max. 500 characters)					no

	Clean	Undamaged	Working	Agrees?	
skirting boards	☐	☐	☐	☑	
	☒	☒	☒	☐	
Comments (Max. 500 characters)					yes

	Clean	Undamaged	Working	Agrees?
floor coverings	☐	☐	☐	☐
	☒	☒	☒	☒

Comments
(Max. 500 characters)

no

Additional Comments

not toally agree with landlord. please check picture.

Additional Comments

(Max. 500 characters)

testing

Security and Safety

	Clean	Undamaged	Working	Agrees?
external door locks	☑	☑	☑	☐
	☐	☐	☐	☒

Comments
(Max. 500 characters)

	Clean	Undamaged	Working	Agrees?
window locks	☑	☑	☑	☐
	☐	☐	☐	☒

Comments
(Max. 500 characters)

Additional Comments

test

Additional Comments (Max. 500 characters)	testing

General

	Clean	Undamaged	Working	Agrees?
heating/air conditioning	☑	☐	☑	☑
	☐	☒	☐	☐

Comments (Max. 500 characters)		test

	Clean	Undamaged	Working	Agrees?
staircase/handrails	☑	☑	☐	☐
	☐	☐	☒	☒

Comments (Max. 500 characters)		

Additional Comments	

Additional Comments (Max. 500 characters)	testing

Health Issues

Are there are any signs of mould and dampness?	Yes	No	Agrees? no

Are there any pests and vermin?	Yes	No	Agrees? yes
Has any rubbish been left on the premises?	Yes	No	Agrees? no

Communication Facilities

a telephone line is connected to the residential premises	Yes	No	Agrees? yes
an internet line is connected to the residential premises	Yes	No	Agrees?

Water Efficiency Devices

all showerheads have a maximum flow rate of 9 litres per minute	Yes	No	Agrees?

all water taps and single mixer taps hand basins have a maximum flow rate of 9 litres per minute	Yes	No	Agrees?
no leaking taps on residential premises	Yes	No	Agrees?

Water meter reading: 234

Health Issues

Additional Comments

(Max. 500 characters)

testing

Communication Facilities

Additional Comments

(Max. 500 characters)

testing

Water Efficiency Devices

Additional Comments

(Max. 500 characters)

testing

Approximate dates when work last done on residential premises

Installation of water efficiency measures:

Painting of premises (external):

Painting of premises (internal):

Flooring laid/replaced/cleaned:

Landlord’s promise to undertake work:

(Skip if not required)

The landlord agrees to undertake the following cleaning, repairs, additions or other work during the tenancy:

The landlord agrees to complete that work by:

Landlord Signature



Signed by Landlord on:23/11/2023 12:07:48

Tenant Signature



Signed by Tenant on:24/11/2023 16:13:18

Bedroom

Photos added by Landlord



Photos added by Tenant



Security and Safety

Photos added by Landlord



Photos added by Tenant



General

Photos added by Landlord



Photos added by Tenant

