

Efficiency Report

Detector Name	XLB1_D1P1
Alpha Eff	0 +/- 0 %
Alpha Spilldown	0 +/- 0 %
Beta Eff	45.3 +/- 1.9 %
Beta SpillUp	0.993 +/- 0.196 %
Alpha Voltage	---
Beta Voltage	1410
Alpha Bkg	0 +/- 0 %
Beta Bkg	0 +/- 0 %

Device: XLB1**Calibration:** AB Air Filter Calibration**Detector:** XLB1_D1P1**Procedure:** Daily Source Check**Batch ID:** Batch_4475**Count Mode:** Simultaneous**Group:** B**Carrier ID:** 2

<u>Sample Name</u>	<u>Assay date</u>	<u>Standard</u>	<u>Live Time (m)</u>	<u>Alpha (CPM)</u>	<u>Beta (CPM)</u>	<u>Efficiency</u>	<u>Spillover</u>	<u>Decay Corrected Activity</u>
Calibration Check_14358	1/2/2024 10:12:55 AM	Sr-90/Y-90 120914	10	2.6 +/-0.51	262 +/-5.12	45.3 % +/-1.9 %	0.993 % +/-0.196 %	9.64 Bq

CK 1/2/2024