

NJ Safety Voyager Top SRI & Mileposts by Sun Glare

Year Range: 2015 - 2020 **Location:** New Jersey State

Physical Condition

	Surfa		ар.		Mod. In	jury	,	Compl	. Pain	Prop.	Dmg.	Total
Road	Surfa	ce]	Гуре	1						1		F
	Wet						Water	Sand	Oil/Fuel		Dirt, Gravel	
	oncrete	^		Blackto	p		Gravel	S	teel Grid	Dirt	N/A	Total
0			5			0		0		0	0	5
0			4			0		0		0	0	4
0			4			0		0		0	0	4
0			4			0		0		0	0	4
0			4			0		0		0	0	4
0			4			0		0		0	0	4
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0			3			0		0		0	0	3
0	 U 	U	3	U	U	0	U	0	U	0	0	3

Concrete	Blacktop	Gravel	Steel Grid	Dirt	N/A	Total
0	3	0	0	0	0	3
0	3	0	0	0	0	3

Road Horizontal Alignment

Straight	Curved Left	Curve Right	N/A	Total
5	0	0	0	5
4	0	0	0	4
4	0	0	0	4
4	0	0	0	4
4	0	0	0	4
4	0	0	0	4
3	0	0	0	3
3	0	0	0	3
2	0	1	0	3
2	1	0	0	3
3	0	0	0	3
1	0	2	0	3
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3
1	0	2	0	3
3	0	0	0	3

Straight	Curved Left	Curve Right	N/A	Total
3	0	0	0	3
3	0	0	0	3
3	0	0	0	3

Road Grade

Level	Down Hill	Up Hill	Hill Crest	Sag (Bottom)	N/A	Total
1	0	0	1	0	3	5
0	0	0	1	1	2	4
3	0	0	0	0	1	4
2	0	2	0	0	0	4
3	0	1	0	0	0	4
4	0	0	0	0	0	4
3	0	0	0	0	0	3
3	0	0	0	0	0	3
1	1	0	0	0	1	3
3	0	0	0	0	0	3
2	0	0	0	0	1	3
0	0	3	0	0	0	3
3	0	0	0	0	0	3
2	0	1	0	0	0	3
1	0	1	1	0	0	3
3	0	0	0	0	0	3
3	0	0	0	0	0	3
1	0	0	2	0	0	3
1	0	2	0	0	0	3
3	0	0	0	0	0	3

Level	Down Hill	Up Hill	Hill Crest	Sag (Bottom)	N/A	Total
3	0	0	0	0	0	3
2	1	0	0	0	0	3
3	0	0	0	0	0	3
2	0	1	0	0	0	3
3	0	0	0	0	0	3