

# Vehicle History Report



ALTO 2015  
WBAWZ510700L22028



Color

Vehicle Color has been changed.



Repairs

Some major repairs has been done.



Good History

History is well-maintained with this vehicle.



Age

Vechicle is under 10 years old.

## Vehicle information

Make

SUZUKI

Model

X3

Version

F25

Model year / Build year

2015 / 2015

Vehicle Type

SPORT UTILITY VEHICLE

Doors number / Standard Seating

5 / 5

Total cylinder capacity

2.0 l / 1995 cm<sup>3</sup>

Engine power

140 kW / 190 HP

Fuel type

DIESEL

## Vehicle history

Vehicle past records found in databases



DATE OF PRODUCTION:

2015-10

VEHICLE AGE:

5 years 6 months

DATE ^

DESCRIPTION

2015-10



PRODUCTION OF THE VEHICLE

2017-09



REPAIR HEAD GASKET REPLACEMENT  
VEHICLE INCIDENT:



ODOMETER READINGS: 59000 km

2017-10



ODOMETER READINGS: 58881 km



VEHICLE COLOR : BROWN  
INTERIOR : BROWN

2018-04



ACCIDENT BUMPER DAMAGE  
VEHICLE INCIDENT: FRONT-LEFT , FRONT-RIGHT , FRONT , INTERIOR , LEFT-SIDE



ODOMETER READINGS: 59500 km

DATE



DESCRIPTION  
ODOMETER READINGS: 50000 km



# Odometer readings

Historical vehicle mileage readings recorded in databases




DATE OF READ:2019-08

MILEAGE READING:73938 km

RESULT OF THE VERIFICATION:A PROBLEM WAS DETECTED

Recorded mileage of the vehicle



DATE	ODOMETER	DESCRIPTION
2017-09	59000 km	
2017-10	58881 km	
2018-04	59500 km	
2018-04	50000 km	
2019-08	73938 km	

# Vehicle equipment

List of vehicle equipment options

- ☒ ALLOY WHEELS

☒ CRUISE CONTROL

☒ AIR CONDITION

☒ HEATED SEATS

☒ POWER ADJUSTABLE EXTERIOR MIRROR

☒ POWER STEERING

☒ ESP

☒ AIR BAGS

☒ LEATHER STEERING WHEEL

☒ ASR

☒ START/STOP SYSTEM
- ☒ CD DRIVE

☒ ENGINE IMMOBILIZER

☒ HEATED MIRRORS

☒ NAVIGATION SYSTEM

☒ POWER DOOR LOCKS

☒ POWER WINDOWS

☒ TRACTION CONTROL

☒ FLOOR MATS

☒ FOG LIGHTS

☒ AIR CURTAINS

☒ MULTIFUNCTIONAL STEERING WHEEL

GROUP	CODE	DESCRIPTION
	0698	AREA-CODE 2 FOR DVD
	01CC	AUTO START/STOP FUNCTION
	0534	AUTOMATIC AIR CONDITIONING
	0205	AUTOMATIC TRANSMISSION
	0316	AUTOMATIC TRUNK LID MECHANISM
	0536	AUXILIARY HEATING
GROUP	CODE	DESCRIPTION
	02K0	BMW 1A WHEEL - V SPOKE 304

01CD	BRAKE ENERGY REGENERATION
0322	COMFORT ACCESS
0544	CRUISE CONTROL WITH BRAKE FUNCTION
0320	DELETED, MODEL LETTERING
04U2	DRIVING EXPERIENCE SWITCH INCL. ECO PRO
0223	DYNAMIC DAMPER CONTROL
0230	EXTRA PACKAGE, EU-SPECIIFC
0423	FLOOR MATS VELOURS
0520	FOG LIGHTS
06NH	HANDS-FREE SYSTEM WITH USB INTERFACE
0676	HIFI SPEAKER SYSTEM
0216	HYDRO STEERING-SERVOTRONIC
06AC	INTELLIGENT EMERGENCY CALL
0431	INTERIOR MIRROR WITH AUTOMATIC-DIP
04CG	INTERIOR TRIM STRIPS "SATIN-SILBER" MATT
0548	KILOMETRE SPEEDO
0851	LANGUAGE VERSION GERMAN
0563	LIGHT PACKAGE
0413	LUGGAGE COMPARTMENT NET
0488	LUMBAR SUPPORT, DRIVER AND PASSENGER
0249	MULTIFUNCTION F STEERING WHEEL
0801	NATIONAL VERSION GERMANY
0606	NAVIGATION SYSTEM BUSINESS
0879	ON-BOARD LITERATURE, GERMAN
09AA	OUTER SKIN PROTECTION
07RS	PACKAGE COMFORT
0508	PARK DISTANCE CONTROL
05DA	PASSENGER AIRBAG DEACTIVATION
02VG	PERFORMANCE CONTROL
0521	RAIN SENSOR
0494	SEAT HEATING DRIVER/PASSENGER
01CA	SELECTION OF COP-RELEVANT VEHICLES
0481	SPORTS SEAT
0240	STEERING WHEEL, LEATHER
0420	SUN PROTECTION GLAZING
06AE	TELESERVICES
0465	THROUGH-LOADING SYSTEM
03AC	TRAILER COUPLING
04NG	TRIMS, DASHBOARD, MIRROR-FINISH
02VB	TYRE PRESSURE DISPLAY
02VL	VARIABLE SPORT STEERING
0428	WARNING TRIANGLE AND FIRST AID KIT
08KA	OLWARTUNGSINTERVALL 24 MONATE/30.000 KM

## Clarifications and reservations

- The reports on vehicles provide information on events related to these vehicles, which we refer to as ‘incidents’. This means significant events concerning the vehicle which may have an impact on the assessment of its technical condition or value, in particular loss events, repairs (both warranty and post-warranty) or maintenance actions. The incident description may include in particular the value of loss or repair in line with the actually incurred costs or their valuation, as well as vehicle odometer reading. Valuations may be prepared e.g. for the owner, insurance company or workshop, e.g. for the purpose of court proceedings. If there are several incidents revealed in a report, they usually refer to different events, but they may also concern the same event, e.g. a few valuations prepared at different times for different insurance companies, workshops, or for the owner.
- The scope of data in the report, including the occurrence of incidents, is made available before buying the report, in its part that is free-of-charge. Data in a report are presented based on the information available for use at a particular moment, concerning a specific VIN number. They originate from various types of databases, generally available information (in particular on the Internet) and own sources. These data may not be up-to-date as of the moment of sharing in our report, because they had been collected earlier and may change over time, in particular as a result of the

vehicle use and incidents. Data on the latest events concerning the vehicle may not be available yet. Despite our efforts to make reports as up-to-date and complete as possible, it is not possible to verify the data included therein with the actual (technical) status of the vehicle as of the date of generating the report. It may also happen that the data were incorrectly recorded at the source, and  
e y t e data c uded t e e t t e actua (tec ca ) status o t e e c e as o t e date o ge e at g t e epo t. t ay a so appe t at t e data e e co ect y eco ded at t e sou ce, a d our report unfortunately repeats this error, which we are not able to verify. Due to this, our system and reports on vehicles obtained from it shall be regarded only as a supporting tool for assessment of the history and condition of a particular vehicle, and then the actual condition and documents related to this vehicle should always be examined directly, particularly before the decision to purchase it.

- 3. In the case of noticing any discrepancies between the vehicle data in the report and the actual status, please inform us about it immediately.
- 4. The history of checking a specific VIN number in our service as stated in reports concerns verification in paid and free-of-charge versions. It does not contain complete or current data, because it is supplemented with certain delay in comparison with the current condition for technical reasons.
- 5. We make efforts to ensure that our original translation system contains a complete and logical translation of source data to all languages observing grammar rules, but due to the automatic nature of translation, the effects may contain words in foreign languages or language errors.  
All content and graphic signs included in the report and our websites are protected with copyrights that belong to Autoiso sp. z o.o.
- 6. The complete legal information concerning the report is provided in the Rules and Regulations that are available on our website.