AI Auto-Diagnostics & RUL Engine

Vehicle Diagnostic Report

Vehicle: **example_vehicle_telemetry.csv**

Generated: 2026-10-05 16:03:06

Model version: v1.0

Vehicle Health

Health Score: **60.0** (FAIR)

Anomaly Analysis

Status: **CRITICAL** Anomaly ratio: 1.0

Sensor	Z-score
coolant_temp_c	0.883
oil_pressure_kpa	0.835
fuel_rate_lph	0.829

Sensor Fault Analysis

Verdict: **NO_SENSOR_FAULT_DETECTED** (confidence 0.0)

Maintenance Recommendation

Cooling System — Coolant Leak Diagnosis

Symptoms: Visible coolant puddle under vehicle, Coolant odor in cabin

Cooling System — Heater Hose

Symptoms: Coolant odor in cabin, Visible coolant leak under vehicle

Cooling System — Coolant/Antifreeze

Symptoms: Engine overheating, Coolant leaks under the vehicle

---

Disclaimer: This report is generated by an automated diagnostic system for demonstration and educational purposes. It does not replace inspection by a certified technician. RUL figures (where shown) are validated on NASA turbofan engine data, not passenger-vehicle run-to-failure data.