

**INSPECTION CERTIFICATE**Report Registration No: **315166**Job Order No.: **JOD-2026-06-44964**

This is to state that, a representative of our organization did at the request of M/s. **Silver Line Construction & Machinery Rental LLC.** on the **10/06/2026** attended their facility in **DIC, Dubai** to carry out the functional and operational test of the below stated equipment and report as follows:

1- Item Inspected



Description :	Diesel Engine Driven, Air Compressor
Inspection Location:	DIC, Dubai
Make:	Hokuetsu Industries Co., Ltd
Model / Type:	PDS265S-4B2
Year of Manufacture:	N/A
Serial No.:	55-4B21611 (SA 334)
Owner's ID:	SA 334
Rated Power Output (kW/kVA)	61.2 kW
M.A.W.P (psi/bar)	0.69 MPa
Engine Make & Model:	Yanmar & 4TNV98T-NHK
Engine Serial No.	217722

2- Inspection Carried Out:

1. Visual Examination of the Equipment Condition
2. Witness the operational & performance test

3- Inspection / Test Result:

The performance test of the above mentioned item was carried out in accordance with the manufacturers recommendations and found to be Acceptable & fit to use.

I CERTIFY THAT the item described above was examined in the prescribed manner and all parameters mentioned above were correct at the time of inspection.				
Name of the competent person:	Muthukumar Muniyan Inspection Engineer		Reviewed by:	Ezhilarasan Asaithambi (07) Team Leader
Signature / stamp:			Signature / stamp:	
Inspection date:	10/06/2026		Inspection due on:	09/06/2027

**INSPECTION CERTIFICATE**Report Registration No: **315166**Job Order No.: **JOD-2026-06-44964**

Critical Points	Condition Found			
Items	S	NS	N/A	Remarks
Safety relief valve	☒	☐	☐	
General Condition	☒	☐	☐	
Legible Markings	☒	☐	☐	
Gauges	☒	☐	☐	
Doors & Hinges	☒	☐	☐	
Cleanliness	☒	☐	☐	
Fuel Tank	☒	☐	☐	
Radiator	☒	☐	☐	
Battery	☒	☐	☐	
Electrical	☒	☐	☐	
Engine	☒	☐	☐	
Hoses & Fittings	☒	☐	☐	
Exhaust System	☒	☐	☐	
Fire Extinguisher	☒	☐	☐	

Legends: • S - SATISFACTORY • NS - NOT SATISFACTORY • N/A - NOT APPLICABLE

Remarks (if any)

