

Bay Battery & Electric

Oakland, CA

SERVICE RECORD

SR-260919-03

2026-09-19

Vehicle	2018 Ford Escape	Mileage	76,980
Customer concern	Slow cranking in the morning.	Record type	Service Record

Technician findings

- Battery failed load test.
- Charging voltage within normal range after replacement.

Status	Work performed	Parts	Labor	Line total
Completed	Performed battery and charging system test	-	0.5h x \$150.00 = \$75.00	\$75.00
Completed	Installed AGM battery	\$249.00	0.3h x \$150.00 = \$45.00	\$294.00

Parts subtotal	\$249.00
Labor subtotal	\$120.00
Subtotal	\$369.00
Sales tax	\$23.66
Total	\$392.66

Recommendations

- Return if slow-crank symptom reappears.

Warranty: Battery warranty: 36 months, subject to manufacturer terms.

Notes: Old battery returned for core credit.