RoadGuard road_damage report
Input: WhatsApp Video 2026-11-05 at 3.35.19 AM.mp4
Status: completed
Model revision: 40684513b39331fc2b49f01123cc489ad5876624
Device: cpu | Runtime: 5.875 seconds
Input SHA-256: 0fcc045e604b49c9f04880cf5ee4f49a3e37c61be4c4e94e37e1bb24d1d1bca5
Weights SHA-256: bcbaa230a4fce93c15cfd1dd4e6bb40050ce9099750ea66e270f00c10ecfdcc6
Settings: {"confidence":0.25,"iou":0.45,"sample_interval_s":1.0,"classes":null}
Observations: 0