RoadGuard road_damage report
Input: WhatsApp Video 2026-11-05 at 3.35.20 AM.mp4
Status: completed
Model revision: 40684513b39331fc2b49f01123cc489ad5876624
Device: cpu | Runtime: 2.469 seconds
Input SHA-256: 2eba29ef8d5f51ea4708c69b0508242a631075e267ff2ca591a183f6a62f4c52
Weights SHA-256: bcbaa230a4fce93c15cfd1dd4e6bb40050ce9099750ea66e270f00c10ecfdcc6
Settings: {"confidence":0.25,"iou":0.45,"sample_interval_s":1.0,"classes":null}
Observations: 3
4.00s pothole conf=0.38902 review=pending
7.00s pothole conf=0.37253 review=pending
7.00s pothole conf=0.27208 review=pending