RoadGuard road_damage report
Input: forward_highway.mp4
Status: completed
Model: 40684513b39331fc2b49f01123cc489ad5876624
Runtime: 27.0 seconds
Observations: 10
0.00s longitudinal_crack conf=0.75993 review=uncertain
1.00s longitudinal_crack conf=0.40628 review=pending
3.00s longitudinal_crack conf=0.30816 review=pending
4.00s longitudinal_crack conf=0.29239 review=pending
8.00s longitudinal_crack conf=0.27189 review=pending
14.00s longitudinal_crack conf=0.436 review=pending
16.00s longitudinal_crack conf=0.50803 review=pending
17.00s longitudinal_crack conf=0.41264 review=pending
20.00s longitudinal_crack conf=0.52676 review=pending
20.00s longitudinal_crack conf=0.42636 review=pending