RoadGuard road_damage report
Input: intersection.jpg
Status: completed
Model revision: 40684513b39331fc2b49f01123cc489ad5876624
Device: cpu | Runtime: 1.5 seconds
Input SHA-256: 38ae53b9d2e0a71993406bcfd29df1a9f6198b89dcb54a90887d47bbff80a58e
Weights SHA-256: bcbaa230a4fce93c15cfd1dd4e6bb40050ce9099750ea66e270f00c10ecfdcc6
Settings: {"confidence":0.25,"iou":0.45,"sample_interval_s":1.0,"classes":null}
Observations: 0