RoadGuard road_damage report
Input: forward_highway.mp4
Status: completed
Model revision: 40684513b39331fc2b49f01123cc489ad5876624
Device: cpu | Runtime: 17.562 seconds
Input SHA-256: ac81100d9310bd4e9c02bc0b13b6492781d009742ced347766b2601be3c44ad4
Weights SHA-256: bcbaa230a4fce93c15cfd1dd4e6bb40050ce9099750ea66e270f00c10ecfdcc6
Settings: {"confidence":0.25,"iou":0.45,"sample_interval_s":1.0,"classes":null}
Observations: 10
0.00s longitudinal_crack conf=0.75993 review=pending
1.00s longitudinal_crack conf=0.40628 review=pending
3.00s longitudinal_crack conf=0.30816 review=pending
4.00s longitudinal_crack conf=0.29239 review=pending
8.00s longitudinal_crack conf=0.27189 review=pending
14.00s longitudinal_crack conf=0.436 review=pending
16.00s longitudinal_crack conf=0.50803 review=pending
17.00s longitudinal_crack conf=0.41264 review=pending
20.00s longitudinal_crack conf=0.52676 review=pending
20.00s longitudinal_crack conf=0.42636 review=pending