



SAMPLE DOCUMENT · Fictitious data for demonstration only. Not an official inspection record.

1. Store information

COMPANY

Sample Restaurant Chain S.A.C. (fictitious)

STORE

#014 · Miraflores, Lima

KITCHEN LINES

2

MONITORING SINCE

March 2026

EDGE GATEWAY

GW-014-A · offline-first

REPORT PERIOD

September 2026

2. Monitored circuits and alarm thresholds

CIRCUIT	SENSORS	LEAKAGE ALARM	LIMIT	STATUS
Fryer bank	Current + leakage	30 mA	40 A	Configured
Grill & griddle	Current + leakage	30 mA	32 A	Configured
Walk-in cooler	Current + temperature	—	6 °C max	Configured
Hood & HVAC	Current	30 mA	25 A	Configured
Ice machine	Current + leakage	30 mA	16 A	Configured
Combi oven 01	Current + leakage	30 mA (safe default)	—	Pending configuration

3. Safe-to-Clean compliance

30 of 30 night washdowns in September 2026 started after a passed Safe-to-Clean check. Every wet zone read 0 mA of leakage and the panel ground continuity test passed on each check.

4. Incidents and maintenance

ID	OPENED	EQUIPMENT	DESCRIPTION	SLA	STATUS
INC-2291	2026-09-27 23:41	Fryer 02	Insulation wear · 18 mA leakage, early alarm	4 h	WO-1182 · electrician dispatched
INC-2288	2026-09-18 21:12	Walk-in cooler	Temperature above 6 °C	8 h	Technician assigned

5. Documents the store must attach

- Certificate of the electrical installation signed by a licensed electrical engineer.
- Test records of the residual-current devices (RCD) protecting each kitchen circuit.
- Building safety inspection certificate (ITSE), where applicable.

This dossier compiles monitoring evidence. It does not replace the certificates and inspections required by law.