

Traditional Search & Rescue Fails Across 4 Critical Voids

70% CANOPY CRASHES

15-30m GEO ERROR

2-3 HOURS DELAY

₹40L+ MILITARY AIRFRAMES



GPS MULTI-PATH

SUBSYSTEM A // GNC

Canopy GPS Drift & Crashes

CORE FAILURE MECHANISM:

Dense foliage blocks satellite GNSS signals

OPERATIONAL IMPACT:

Commercial flight controllers lose position lock, drifting into tree canopies and causing catastrophic rotor loss.

70% Loss

Canopy Sorties

0 Hold

Non-GPS Stability

TARGET: PX4 & 3D ORCA

LEAD: NIKHIL



DIGITAL CLIFF

SUBSYSTEM B // COMMS

Mountain Ravine RF Blackout

CORE FAILURE MECHANISM:

Ridgelines sever direct line-of-sight RF

OPERATIONAL IMPACT:

Conventional H.264 digital video completely cuts out below 5dB SNR, plunging base operators into total blindness.

<5dB SNR

Video Blackout

0 Relay

Single-Drone Link

TARGET: DEEP JSCC MESH

LEAD: NIKHIL



35% FALSE ALARMS

SUBSYSTEM C // VISION

Flat-Earth Elevation Drift

CORE FAILURE MECHANISM:

2D raycasts assume flat zero-elevation ground

OPERATIONAL IMPACT:

Sloping terrains produce 15-30m calculated coordinate errors, routing emergency ground teams to empty ravines.

15-30m

Location Drift

35%

False Alarm Rate

TARGET: 3D DEM RAYCAST

LEAD: VEDANTH



15-25 CREW LOAD

SUBSYSTEM D // C2 GCS

Central Pilot Bottleneck

CORE FAILURE MECHANISM:

1-pilot-per-drone manual radio control

OPERATIONAL IMPACT:

Requires 15-25 field personnel and 45-90 min setup; sortie collapses immediately if the single pilot link drops.

2-3 Hrs

Search Time / mi²

₹12.5L

Cost / Deployment

TARGET: WEBGPU ATAK GCS

LEAD: SIVA