



GPS Loss and Radio Blackouts Cripple Disaster Rescue

- Mountain valleys cut drone video feeds
- Dense trees block satellite GPS signals
- Single control towers cause mission failure
- Manual searching delays finding trapped victims
- Military drones cost over ₹40 Lakhs each

SUBSYSTEM FAILURE SCHEMATICS & TARGET MOAT



SUBSYSTEM A VOID
Canopy GPS Drift
GNSS Multi-Path Crash



SUBSYSTEM B VOID
RF Ridge Cut
Digital Cliff Blackout




SUBSYSTEM C/D VOID
Central Link Abort
Single Point Swarm Loss

3 SYSTEM VOIDS

REAL DISASTER FIELD EVIDENCE

SOURCE 01 / 03



Wayanad Landslide Search

Western Ghats • NDMA Official Disaster Review

FIELD BOTTLENECK

"70% of commercial drones lost connection behind mountain ridges and crashed under thick tree canopy."

CONTINUOUS LOOP