

SRI HAMSINI & CHANDRA ENTERPRISES

Office Address: 2-1-49/244, Park Street, Street No. 17, Suryanagar Colony, Uppal, Hyderabad, Telangana - 500039

WATER PURIFICATION UNIT: INSTALLATION / COMMISSIONING / SERVICE / VISIT REPORT

Serial No: PENDING VERIFICATION	Report No: Service	Visit Date: 2026-07-28	Complaint No: 5	Unit Type: AMC
CUSTOMER NAME & ADDRESS:	PROBLEM REPORTED:		OBSERVATION & ACTION TAKEN:	
MALLAVOLU	Service product water not coming		Checking filters and replacing 2mcf and cleaning filters and Checking fr good and observation of all leakages good and replacing 1 floaty	
		SPARES REQUIRED: 2.mcf,1.floaty		
UNIT DETAILS / SITE CONDITION		PLANT READINGS		
Plant Location	MALLAVOLU	Raw Water TDS	1317	
Plant Capacity	100lph	Product Water TDS	97	
Design R/W TDS	1317	Product Water Flow in LPH	100.0	
Free Chlorine in R/W	No	Sensors Condition	OK	
No. of Hours Running	3hrs	Pre-Filter Condition	OK	
Membrane Condition	OK	Voltage	230.0	
UV Lamp Condition	OK	Current in Amps	24	
SPARES CONSUMED				
2.mcf,1.floaty				
CUSTOMER NAME / MOBILE NUMBER	CUSTOMER SIGNATURE & DATE		SCHOOL STAMP	
Mallavolu 8919455107			(no stamp on file)	
SERVICE ENGINEER: SUNNY		STATUS: PROBLEM RESOLVED		
SERVICE ENGINEER SIGNATURE:				
Customer Remarks: —				

E-mail Id: ch.srini1979@yahoo.com / ch.srini1979@rediffmail.com Tel No. 7670873623