COIMBATORE CITY MUNICIPAL CORPORATION - CIVIC SAFETY NOTICE

OFFICIAL EVIDENCE ATTACHMENT - COMMUNITY SAFETY RECORD

Inspection Docket: CCMC/ENG/2026/HAZ-441

Ward: Ward 23, West Zone, R.S. Puram

Location: 4th Street Crossway connecting East Ramalingam Road

Inspection Officer: Junior Engineer (Public Works Department)

Observation: Overgrown tree branches completely covering street fixtures.

High risk of purse-snatching and unwanted harassment after 7:30 PM.

Recommendations: Immediate pruning of tree canopy and installation of 2 LED flood fixtures.

Notice issued to TANGEDCO for feeder line check.

Document verified by SafePass Women Safety Cloud Portal - Timestamped on Cloud Storage