WOMEN COMMUTER SAFETY AUDIT & INFRASTRUCTURE REPORT

OFFICIAL EVIDENCE ATTACHMENT - COMMUNITY SAFETY RECORD

Audit Title: Night Commuter Safety & Pedestrian Route Audit

Auditing Body: Tamil Nadu Women Commuter Safety Initiative & Local Ward Volunteers

Location: Singanallur Junction Pedestrian Underpass (Trichy Road)

Safety Score: 22/100 (HIGH RISK CRITICAL)

Key Findings:

- 4 out of 5 tube lights smashed / defunct
- Zero police presence or security guard stationed after 8:00 PM
- Water logging during rains forcing women to walk along the highway carriageway

Action Required: Urgent deployment of Pink Patrol vehicle and CCTV integration.

Document verified by SafePass Women Safety Cloud Portal - Timestamped on Cloud Storage