

WATER REPORT

SAMPLE COLLECTION DATE: 09-06-2026
SAMPLE ANALYSIS DATE: 12-06-2026
CLIENT NAME: Shree Prakash Textiles
ADDRESS: 601 B, Neelyog Square, R. B. Mehta Marg,
Ghatkopar East, Mumbai
CONTACT PERSON: Mr. R

RO FEED WATER & RO 3RD STAGE REJECT WATER ANALYSIS REPORT

Dear Sir,

Please find below the water analysis results for Shree Prakash Textiles. The measured parameters for the submitted samples are presented for your review.

PARAMETER	UNIT	RO FEED WATER	RO 3RD STAGE REJECT WATER
pH	Mg/L	1,250	10,000
TDS	Mg/L	1,250	10,000
Total Hardness as CaCO ₃	Mg/L	1,250	10,000
T Alkalinity as CaCO ₃	Mg/L	1,250	10,000
Chloride as Cl	Mg/L	1,250	10,000
Sulphate	Mg/L	1,250	10,000
Phosphate as PO ₄	Mg/L	1,250	10,000
Calcium	Mg/L	1,250	10,000
Magnesium	Mg/L	1,250	10,000

REMARKS

- Water sample was clear.
- pH value was within the specified range.
- TDS of reject water is high.

For,

Nirmaan WaterTech Solutions



Ritesh Dantani

info@nirmaanwatertech.com