

Report ID: RDS-20260615003226

SMART ROAD DAMAGE DETECTION REPORT

Detection Result



Parameter	Value
Total Potholes	2
Severe	2
Medium	0
Minor	0
Confidence	89.95%

Road Health Score: 60%

Road Status: ■ Fair

Image Name: 01_jpg.rf.311d897b199b9edde57b99bc4b606074.jpg

Date: 15-06-2026 00:32:26

Total Potholes: 2

Severe Potholes: 2

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 89.95%

Generated by Smart Road Damage Detection System

YOLOv8 | *OpenCV* | *Flask*