

Smart Road Damage Detection Report

Image Name: 01_jpg.rf.bf7e43382a861a8c57127bca8c177a2d.jpg

Date: 2026-06-06 15:55:26.055030

Total Potholes: 2

Severe Potholes: 2

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 89.99%