


Report ID: RDS-20260624023648

SMART ROAD DAMAGE DETECTION REPORT

Detection Result



Parameter	Value
Total Potholes	2
Severe	2
Medium	0
Minor	0
Confidence	89.99%

Road Health Score: 60%

Road Status: ■ Fair

Image Name: 01_jpg.rf.bf7e43382a861a8c57127bca8c177a2d.jpg

Date: 24-06-2026 02:36:48

Total Potholes: 2

Severe Potholes: 2

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 89.99%

Generated by Smart Road Damage Detection System

YOLOv8 | *OpenCV* | *Flask*