

Report ID: RDS-20260608171738

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	2
Severe	2
Medium	0
Minor	0
Confidence	86.53%

Road Health Score: 60%

Road Status: ■ Fair

Image Name: 07_jpg.rf.65ebea5150fe68de799738c5417e8c65.jpg

Date: 08-06-2026 17:17:38

Total Potholes: 2

Severe Potholes: 2

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 86.53%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask