

Report ID: RDS-20260608171608

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	0
Medium	1
Minor	0
Confidence	82.6%

Road Health Score: 90%

Road Status: ■ Excellent

Image Name: 106_jpg.rf.af8d759f741fb96ce70d3d31616b1894.jpg

Date: 08-06-2026 17:16:08

Total Potholes: 1

Severe Potholes: 0

Medium Potholes: 1

Minor Potholes: 0

Average Confidence: 82.6%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask