


SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	6
Severe	2
Medium	4
Minor	0
Confidence	83.22%

Road Health Score: 20%

Road Status: ■ Poor

Image Name: 127_jpg.rf.f0ad48165ae1c0fcbc4c7dc0a3d7b0c5.jpg

Date: 08-06-2026 17:14:59

Total Potholes: 6

Severe Potholes: 2

Medium Potholes: 4

Minor Potholes: 0

Average Confidence: 83.22%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask