


SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	12
Severe	0
Medium	7
Minor	5
Confidence	76.67%

Road Health Score: 5%

Road Status: ■ Poor

Image Name: 141_jpg.rf.e62c942d5f530cc7b09d2eb843acf494.jpg
Date: 08-06-2026 17:17:16
Total Potholes: 12
Severe Potholes: 0
Medium Potholes: 7
Minor Potholes: 5
Average Confidence: 76.67%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask