


Report ID: RDS-20260608173540

SMART ROAD DAMAGE DETECTION REPORT

Detection Result



Parameter	Value
Total Potholes	7
Severe	4
Medium	3
Minor	0
Confidence	84.75%

Road Health Score: 0%

Road Status: ■ Poor

Image Name: 16_jpg.rf.3098e2905702714e2a3514cc9ead4f62.jpg

Date: 08-06-2026 17:35:40

Total Potholes: 7

Severe Potholes: 4

Medium Potholes: 3

Minor Potholes: 0

Average Confidence: 84.75%

Generated by Smart Road Damage Detection System

YOLOv8 | *OpenCV* | *Flask*