

Report ID: RDS-20260608171355

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	2
Severe	1
Medium	1
Minor	0
Confidence	82.18%

Road Health Score: 70%

Road Status: ■ Fair

Image Name: 16_jpg.rf.ace2728bca5368783455a899db89b9f2.jpg

Date: 08-06-2026 17:13:55

Total Potholes: 2

Severe Potholes: 1

Medium Potholes: 1

Minor Potholes: 0

Average Confidence: 82.18%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask