


Report ID: RDS-20260615003035

SMART ROAD DAMAGE DETECTION REPORT

Detection Result



Parameter	Value
Total Potholes	6
Severe	1
Medium	5
Minor	0
Confidence	82.43%

Road Health Score: 30%

Road Status: ■ Poor

Image Name: 17814635623583908354404139066771.jpg

Date: 15-06-2026 00:30:35

Total Potholes: 6

Severe Potholes: 1

Medium Potholes: 5

Minor Potholes: 0

Average Confidence: 82.43%

Generated by Smart Road Damage Detection System

YOLOv8 | *OpenCV* | *Flask*