

Report ID: RDS-20260608234706

SMART ROAD DAMAGE DETECTION REPORT

Detection Result



Parameter	Value
Total Potholes	11
Severe	2
Medium	8
Minor	1
Confidence	81.34%

Road Health Score: 0%

Road Status: ■ Poor

Image Name: 17_jpg.rf.43df49bad1838757beb55a58f1eb7152.jpg

Date: 08-06-2026 23:47:06

Total Potholes: 11

Severe Potholes: 2

Medium Potholes: 8

Minor Potholes: 1

Average Confidence: 81.34%

Generated by Smart Road Damage Detection System

YOLOv8 | *OpenCV* | *Flask*