

Report ID: RDS-20260608141623

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	1
Severe	1
Medium	0
Minor	0
Confidence	88.27%

Road Health Score: 80%

Road Status: ■ Excellent

Image Name: 197404.jpg

Date: 08-06-2026 14:16:23

Total Potholes: 1

Severe Potholes: 1

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 88.27%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask