

Report ID: RDS-20260608171433

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	3
Severe	3
Medium	0
Minor	0
Confidence	86.41%

Road Health Score: 40%

Road Status: ■ Poor

Image Name: 21_jpg.rf.9e6ffad2a228077cb840ae800ac0e2af.jpg

Date: 08-06-2026 17:14:33

Total Potholes: 3

Severe Potholes: 3

Medium Potholes: 0

Minor Potholes: 0

Average Confidence: 86.41%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask