


Report ID: RDS-20260608171812

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	6
Severe	1
Medium	3
Minor	2
Confidence	78.44%

Road Health Score: 40%

Road Status: ■ Poor

Image Name: 23_jpg.rf.c06272d948cbce242eeeeab14cb9363d.jpg

Date: 08-06-2026 17:18:12

Total Potholes: 6

Severe Potholes: 1

Medium Potholes: 3

Minor Potholes: 2

Average Confidence: 78.44%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask