

Smart Road Damage Detection Report

Image Name: 24_jpg.rf.b7de35e34c66fd36d34bbb6700efc9bd.jpg

Date: 2026-06-06 16:51:26.486961

Total Potholes: 2

Severe Potholes: 1

Medium Potholes: 0

Minor Potholes: 1

Average Confidence: 79.92%