

Report ID: RDS-20260608171954

SMART ROAD DAMAGE DETECTION REPORT

AI Powered Road Inspection System

Detection Result



Parameter	Value
Total Potholes	3
Severe	1
Medium	1
Minor	1
Confidence	81.96%

Road Health Score: 65%

Road Status: ■ Fair

Image Name: 299.jpg

Date: 08-06-2026 17:19:54

Total Potholes: 3

Severe Potholes: 1

Medium Potholes: 1

Minor Potholes: 1

Average Confidence: 81.96%

Generated by Smart Road Damage Detection System

YOLOv8 | OpenCV | Flask